



5383 Sandhurst Circle North  
 Lake Worth, FL 33463  
 CGC 060027 WWW.PromarBuilding.com  
 Office (561) 819-3900 Fax (561) 431-0238

Carlton House Management Association, Inc.  
 Attn: Board of Directors  
 2701 South Ocean Blvd  
 Highland Beach, Florida 33487

March 26, 2025

**CONTRACT  
 EXTERIOR WALL REPAIR  
 CHANGE ORDER 12 DRAW 5**

	Description	Unit	Unit Price	Quantity This Period	Total Billed to Date
1.1	Partial Depth Slab Repair	SF	\$105.00	74.09	\$ 7,779.45
1.2	Full Depth Slab Repair	SF	\$ 150.00	332.70	\$ 49,905.00
1.3	Partial Depth Overhead Slab Repair	SF	\$ 120.00	16.14	\$ 1,936.80
1.4	Overhead Concrete Beam or Tie-Beam Repair	CF	\$350.00	9.48	\$ 3,318.00
1.6	Vertical Concrete Repair at Walls	CF	\$ 190.00	28.40	\$ 5,396.00
2.2	Stucco Patch Repair	SF	\$ 20.00	960.66	\$ 19,213.20
<b>CHANGE ORDER TOTAL</b>					<b>\$ 87,548.45</b>

Please sign below and email to our office Mgerwig@Promarbuilding.com

**Promar Building Services, LLC**

**Carlton House Management Association, Inc.**

**O & S Associates Engineers**

**Arnaldo Alfredo Amador**

Signature

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Signature

Arnaldo Alfredo Amador, President  
Print Name and Title

\_\_\_\_\_  
Print Name and Title

Alma Liriano-Project Engineer  
Print Name and Title

March 26, 2025  
Date

\_\_\_\_\_  
Date

March 27, 2025  
Date